PASSING SHOT by **SEGA**

COMPONENT			SOLDER
GND	1	A	GND
GND	2	B	GND
+5V	3	C	+5V
+5V	4	D	+5V
+12V	5	E	+12V
Counter 1	6	F	Counter 2
Lamp 1	7	G	Lamp 2
1P.Lob	8	H	2P.Lob
1P.Flat	9	I	2P.Flat
1P.Spin	10	J	2P.Spin
1P.Slice	11	K	2P.Slice
1P.Down	12	L	2P.Down
1P.Up	13	M	2P.Up
1P.Right	14	N	2P.Right
1P.Left	15	O	2P.Left
	16	P	
	17	Q	
	18	R	
	19	S	
Coin 1	20	T	1P.Start
Coin 2	21	U	2P.Start
Test	22	V	
Service	23	W	
Speaker +	24	X	Speaker -
Red	25	Y	Green
Blue	26	Z	Sync
GND	27	a	GND
GND	28	b	GND